

Claim	: 20637
Aircraft	: MD530F helicopter
Location	: GPM Aeroservicio, near Toluca International Airport, State of Mexico
Being offered	: As is where is
Contact Information	: Pablo Bañuelos Marquez; pablomanuelos@aav.global



### Aircraft Details

Serial number 0702FF; the helicopter has a total time since new of 5,201 flight hours. The Allison 250-C30 engine, serial number CAE-900162, has a total time since new of 3,792 flight hours.

### Accident Circumstances

On 19<sup>th</sup> January 2020, while descending to land at the airstrip of the Army Operations Base #1, in Guadalupe y Calvo, Chihuahua, the helicopter descended rapidly, hit the ground with the left landing skid first at a very high rate of descent, the skid broke and rolled over.

### Aircraft Damage

*Please refer to the photographs*

- Deformation and distortion throughout the airframe • All dynamic components are considered scrap • The main rotor blades broke and detached • The undercarriage is scrap; the left skid broke and separated • The tail rotor section broke and detached • The rotating components of the engine are considered scrap.



