

Claim	: 20326
Aircraft	: Gulfstream G200, N813WM
Location	: Tegucigalpa, Honduras
Being offered	: As is where is
Contact Information	: Julio Garcia – juliogarcia@aav.global



Accident Circumstances

On 22nd May 2018, while landing at Toncontin Airport at Tegucigalpa, Honduras, from Austin, Texas, the Gulfstream G200, N813WM, landed too long and went off the end of the runway. The aircraft went through the airport fence, descend the steep slope beyond, collided with a light post and damaged 100 meters of 3 high-tension cables of the electrical power network.

Aircraft Damage

Please refer to the photographs

The aircraft fuselage was distorted and broke into 3 segments. The landing gear was severed. The aircraft was recovered and move for safekeeping at a truck parking lot near the Airport.





